

JULY 2021

REFILLING ORIGINAL CANON CLI-42 YELLOW CARTRIDGE

After testing the PC42SE carefully since 2019, we have come to the conclusion that the PC42SE Yellow ink is now safe to be mixed with the OEM Yellow.

If users wish to be extremely careful, then cleaning out the OEM tanks with Windex or other chemical solutions that completely remove all traces of the original ink will not hurt.

DO NOTE, when the yellow tank has come to a point it needs to be flushed, it would be wise to do so with Windex or other chemicals that aid in cleaning.